

Wolf Lodge Creek Restoration Project Phase 1 – Site 3

Photo Log

Compiled on:
April 27th, 2021

Prepared for:

Avista

Idaho Department of Environmental Quality

Idaho Soil & Water Conservation Commission

Jeff Sells

Mike Murphy

North Idaho Fly Casters

Restoration Partnership

Steve & Janet Funk

TC Energy

Prepared by:

Kootenai-Shoshone Soil and Water Conservation District

7830 Meadowlark Way Suite C1,

Coeur d'Alene, Idaho 83815

Phone: (208) 209-4348

Email: ksswcd@yahoo.com

Wolf Lodge Creek Restoration Project

Phase 1 – Site 3

Pre-construction



Photo 1: Pre-construction 10/31/2019. Right bank and stream channel, facing upstream. Near upstream end of project area. (*IMG_6810.jpg*)



Photo 2: Pre-construction 10/31/2019. Stream channel, facing downstream. Upstream of fence line. (*IMG_6827.jpg*)



Photo 3: Pre-construction 10/31/2019. Left bank and stream channel, facing downstream. Upstream of property owner's structures. (*IMG_6838.jpg*)



Photo 4: Pre-construction. Left bank, facing downstream. Near property owner's structures. (*Murphy Shed.jpg*)



Photo 5: Pre-construction 10/31/2019. Stream channel, facing downstream. Downstream of property owner's structures. (*IMG_6858.jpg*)



Photo 6: Pre-construction 10/31/2019. Stream channel and left bank, facing downstream. Downstream end of property fence line. (*IMG_6880.jpg*)



Photo 7: Pre-construction 2/25/2020. Sourcing wood and identifying staging areas with partners. (*SandySchleppGroup.jpg*)



Photo 8: Pre-construction 7/27/2020. Sourcing wood with partners. (*Prior to Sandy Schlep 07.27.2020.jpg*)

Wolf Lodge Creek Restoration Project

Phase 1 – Site 3

Construction



Photo 9: Construction. Willow harvesting. (*willow and flood plain before shot_Page_4.jpg*)



Photo 10: Construction. Collecting Category 1 wood. (*Cat 1 wood (a).jpg*)



Photo 11: Construction. Staging area. (*Staging Area 1.jpg*)



Photo 12: Construction. Staging area Category 3 wood. (*Cat 2 Staging Area.jpg*)



Photo 13: Construction. Recontouring of stream with Vegetated Wood Matrix Type 1 installation. Left bank, upstream of property owner, facing downstream. (*DownstreamMurphy.jpg*)



Photo 14: Construction. Floodplain treatment (right bank) with Vegetated Wood Matrix Type 1 and 2 installation (left bank). From right bank to left bank, near property owner's structures. (*Upstream looking at Mikes.jpg*)



Photo 15: Construction. Inspection of Vegetated Wood Matrix Type 1 with partners . (1.jpg)



Photo 16: Construction. Streambank access road, left bank. Upstream of landowner property, facing upstream. (11.24.2020.jpg1.jpg)



Photo 17: Construction. Recontouring of stream channel and floodplain enhancement, down stream of landowner property. Viewed from S Wolf Lodge Creek Rd. (*Road view.jpg*)

Wolf Lodge Creek Restoration Project

Phase 1 – Site 3

Post Construction
November 25th, 2020



Photo 18: Post Construction. Installed Vegetated Wood Matrixes near upstream edge of project area, looking downstream. (*PXL_20201125_171322887.jpg*)



Photo 19: Post Construction. Installed Vegetated Wood Matrixes and constructed streambed upstream of property owner's structures. Facing upstream. (*PXL_20201125_172143597.jpg*)



Photo 20: Post Construction. Installed floodplain treatment. Right bank, upstream of property owner's structures, facing downstream. (*PXL_20201125_172422048.jpg*)



Photo 21: Post Construction. Installed Vegetated Wood Matrixes and constructed streambed upstream of property owner's structures. Facing downstream. (*PXL_20201125_172445806.jpg*)



Photo 22: Post Construction. Installed Vegetated Wood Matrixes and constructed streambed downstream of property owner's structures. Facing downstream (*PXL_20201125_173543929.jpg*)



Photo 23: Post Construction. Floodplain treatment downstream of property owner's structures. Left bank, facing downstream. (*PXL_20201125_174233961.jpg*)

Wolf Lodge Creek Restoration Project
Phase 1 – Site 3

Post Construction
Spring Site Visit
April 15th, 2021



Photo 24: Post Construction Spring. Upstream Edge of project, facing downstream. Left bank.
(*Startofprojectarea#2.jpg*)



Photo 25: Post Construction Spring. Inspection with partners of left bank on landowner's property.
(*Murphy#2.jpg*)



Photo 26: Post Construction Spring. Inspection with partners of left bank downstream of landowner's structures. (*Groupshot.jpg*)

Wolf Lodge Creek Restoration Project Phase 1 – Site 3

Pre and Post Construction Comparisons



Photo 27: Pre-Construction. Left bank looking upstream. Downstream of property owner's structures. (*IMG_6840.jpg*)



Photo 28: Post Construction. Left bank looking upstream. Downstream of property owner's structures. (*PXL_20201125_172841635.jpg*)



Photo 29: Pre-Construction. Stream channel, downstream of property owner's structures. Facing downstream. (*willow and flood plain before shot_Page_8.jpg*)



Photo 30: Post Construction. Stream channel, downstream of property owner's structures. Facing downstream. (*PXL_20201125_173122977.jpg*)